



CAUTION



Spindle Shaper

- Keep work area clean.
- Be sure available dust collection system is operating.
- Before you begin:
 - Inspect workpiece for nails, screws, knots, etc.
 - Be sure filler plate/blade gap is no more than 1/8”.
 - Inspect cutter and collets for defects.
- Use proper cutter for material being worked.
- Use jig fixtures to feed material whenever possible.

Note: Immediately report all machinery malfunctions to the supervisor.