



CAUTION



Scroll/Jig Saw

- Keep work area clean.
- Be sure available dust collection system is operating.
- Before you begin:
 - Inspect workpiece for nails, screws, knots, etc.
 - Replace dull, cracked, or excessively fouled saw blades.
 - Be sure filler plate/blade gap is no more than 1/8”.
 - Lower material-hold-down bar as far as thickness of material will allow.
- Use proper saw blade for material being worked.
- Do not force feed material.

Note: Immediately report all machinery malfunctions to the supervisor.